

Appl. No: 10/606,397
Amdt. dated - April 7, 2005
Reply to Office action of January 25, 2005

Amendments to the Specification

Please replace the second paragraph on page 5 with the following amended paragraph:

The corner clamp assembly 25 includes a corner clamp frame or mounting support, generally designated 30, including a pair of right angularly related support or arms 32 and 32A rigidly coupled together via a corner bracket 34. Mounted on the support arms 32 and 32A are clamping members 36 and 36A, respectively. Hereafter, the clamp member 36 will be described in detail with the understanding that the clamp member 36A includes similar parts followed by the reference character A.

Please replace the second paragraph on page 7 with the following amended paragraph:

It will also be assumed that initially only the top trim board 29 and one vertical trim board 33 is disposed adjacent the upper right hand corner of the window frame 14 in the positions illustrated in Figs. 3 and 4. The ~~corner clamp hand~~ trim tool 10 is mounted on the upper right hand corner of the opening frame 14.

Please replace the first paragraph on page 8 with the following amended paragraph:

The clamp ~~frames~~ members 36 and 36A thus react between the window frame 14 and the trim frame 12 to force the trim frame members 29 and 33 together to close the gap at the joint 39. With the trim frame members thus held, the carpenter is free to

use both hands to nail the trim frame members 33 and 29 to the window frame members 26 and 24, respectively.